

ACKNOWLEDGEMENT AND RELEASE

I, the undersigned, have received a copy of a CarFax vehicle history report, a copy of which is attached to this document.

The particulars of the vehicle are as follows:

VIN: 3VW2K7AJ5FM246953#

Make: VOLKSWAGEN

Model: JETTA

Stock No: MMON105934

Report Date: 2022-01-28 12:54:09

I have read the report and understand its contents.

I hereby release Stark Auto Sales from any disclosure obligations with regard to the information contained in the report.

Dated this _____ day of _____, _____.

Customer's Signature: _____

Customer's Name: _____

2015 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas
3VW2K7AJ5FM246953
Country of Assembly: Mexico
Last Reported Odometer: 120,566 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Salvage)



3 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of January 27, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
! 2016 Mar 22	Brampton, Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage Vehicle involved in a rear-end collision with another motor vehicle Damage to front Damage to rear Vehicle towed	
	Estimate: Front Center Estimate Date: 2016 Mar 24 Claim: Collision	\$21,939.62 \$23,714.00
! 2016 Apr 22	Ontario, Canada	
	Claim: Collision	\$12,469.00
! 2017 Sep 7	Etobicoke, Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage Vehicle involved in a sideswipe collision with another motor vehicle Damage to left side	
	Estimate: Left Front Side Estimate Date: 2017 Sep 19 Claim: Collision	\$7,320.05 \$7,956.00
	Damage Repair	\$7,320.05
! 2021 Dec 6	Mississauga, Ontario, Canada	
	Estimate: Total Loss Estimate Date: 2021 Dec 17 Claim: Other Damage	\$8,720.45 \$12,454.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
! 2022 Jan 4	Ontario, Canada	
	Registration Event: Salvage	



Registration

! This vehicle has been registered in the province of **Ontario** in **Canada** with **Salvage** branding.

Details:

Damaged to the extent that cost of repairing the vehicle for legal operation on the public roads exceeds its fair market value immediately prior to damage.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Apr 22	27,892 KM	Sure Fire Automotive Ltd. Brampton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Four wheel alignment performed
2017 Aug 21	60,457 KM	Great Canadian Oil Change Concord, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Tire condition and pressure checked
2020 Nov 23	120,566 KM	Great Canadian Oil Change Concord, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Oil pan drain plug replaced



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Nov 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	First Owner Reported
2014 Nov 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Nov 28		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2015 Apr 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Apr 11		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2016 Mar 22		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none">• moderate damage• Vehicle involved in a rear-end collision• with another motor vehicle• Damage to front• Damage to rear• Vehicle towed
2016 Mar 22		Insurance Records Ontario, Canada		
2016 Mar 22	27,879 KM	Insurance Records Brampton, Ontario, Canada	Estimate Repair	Estimate Date: 3/24/2016 Front Center
2016 Apr 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Apr 11		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2016 Apr 22		Insurance Records Ontario, Canada		
2016 Apr 22	27,892 KM	Sure Fire Automotive Ltd. Brampton, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 21	60,457 KM	Great Canadian Oil Change Concord, Ontario, Canada	Service Record	Vehicle serviced
2017 Sep 7		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none">• moderate damage• Vehicle involved in a sideswipe collision• with another motor vehicle• Damage to left side
2017 Sep 7		Insurance Records Ontario, Canada		

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Sep 7		Repair Facility Rexdale, Ontario, Canada	Repair Record	Repair amount was \$7,320.05
2017 Sep 7	61,781 KM	Insurance Records Etobicoke, Ontario, Canada	Estimate Repair	Estimate Date: 9/19/2017 Left Front Side
2018 Apr 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Apr 11		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Apr 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Apr 11		Motor Vehicle Dept. Ontario, Canada	Previous use	Personal
2020 Nov 23	120,566 KM	Great Canadian Oil Change Concord, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 6		Insurance Records Ontario, Canada		
2021 Dec 6		Insurance Records Mississauga, Ontario, Canada	Estimate Repair	Estimate Date: 12/17/2021 Total Loss
2022 Jan 4		Ontario, Canada	Registration Event	Salvage
2022 Jan 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)